

Interactive comment on “Field-based groundwater recharge and leakage estimations in a semi-arid Eastern Mediterranean karst catchment, Wadi Natuf, West Bank” by Clemens Messerschmid et al.

Clemens Messerschmid et al.

clemensmesserschmid@yahoo.de

Received and published: 26 October 2018

Dear reviewer,

thank you very much for your comments. Please find enclosed - our answers - and an additional file on misreadings best regards, also on behalf of my colleagues,
Clemens Messerschmid

C1

Please also note the supplement to this comment:

<https://www.hydrol-earth-syst-sci-discuss.net/hess-2018-329/hess-2018-329-AC4-supplement.pdf>

Interactive comment on Hydrol. Earth Syst. Sci. Discuss., <https://doi.org/10.5194/hess-2018-329>, 2018.

C2

Some erroneous data readings in the SM-probes

Initial remarks & context:

For our model we measured soil moisture at 8 locations and with two to three sensors at each location, covering different depths between surface (top soil) and bottom soil. All together we measured a total period of 1,818 days of soil moisture readings, spread over all stations of which had wetted soil, i.e. with effective moisture larger than SM_{min} . The total number of days spans over seven years or 2,557 days with modelled SM (for all stations together excluding modelled SM).

After running our parsimonious model we compared observed soil moisture (SM_{obs}) with modelled soil moisture (SM_{mod}) for each location (on example, RK-W is shown in Fig. 4). However, some misreadings occurred, in which observed soil moisture levels (normalized to mm water) were lying above accumulated rainfall, which is physically impossible. Since at the location of runoff, soil or groundwater could be transferred from other areas to the measurement point, high allegedly “observed” SM readings are faulty and constitute machine failure (most likely either the sensors or the loggers).

The important question asked by the reviewers therefore was:

How grave is the error caused by misreadings, how deep its impact?

Some technical problems were encountered at some of the SM stations. During brief periods, the sensors read out wrong soil moisture data (higher than preceding accumulated rainfall). This was observed at stations RK-W, RK-M, and RK-S.